

FITNESS CERTIFICATE OF SCHOOL BUILDING

[To be filled by the Inspecting Officer (Assistant Engineer)]


1. Name of School Sree Narayana Guru Central School,
Ezhukone
2. Location with name of Education District Ezhukone, Kottarakkova
3. Whether the fitness certificate has been issued last year? Yes
4. Classification of the buildings Permanent/Temporary shed? 1) 3 Stoned RCC Building
GF 6.22x6.20x3.75m - 5nos (Class Rooms)
10.15x6.20x3.75m - 2nos (Lab)
3.00x6.20x3.75m - 2nos (Stair)
2.10x6.20x3.75m - 2nos (Stair)
6.48x8.48x3.70m - Porch
31.28x2.40x3.75m } Passage
2x6.71x2.40x3.75m }
FF 6.22x6.20x3.75m - 6nos
12.72x6.20x3.75m - 2nos
SF 9.45x6.20x3.75m - 4nos
6.20x6.20x3.75m - 3nos
5. Year of construction
6. Short specification
7. Whether regular maintenance works attended to or not? Yes
8. Name of officer RAJESH.B.K
9. Period for which the certificate issued 2023-24
10. Nature of defects if any?
 - (a) Foundation and basement
 - (b) Superstructure
 - (c) Roof
 - (d) Floor
 - (e) Miscellaneous


2) 3 Stoned RCC Building
GF, FF, SF { 28.95x6.60x3.60m
2x16.20x6.60x3.60m
28.95x1.85x3.60m
2x16.20x1.60x3.60m
1x6.50x4.60x3.60m

3) Office - single storey, permanent
3.30x3.75x3.60m
3.25x3.75x3.60m
3.35x5.73x3.60m
11. Any major defects noticed which will render the building unsafe if any manner No
12. Whether maintenance works have been done properly? Yes
13. Whether the structure is sound or not to conduct classes? Structure is sound to conduct classes under normal wind and weather conditions

Certified that the building was inspected on 23/05/2023 and found to be fit/unfit to conduct classes for the period for 2023-24 for the reasons stated above.

Place : Ezhukone
Date : 23/05/2023




 Assistant Engineer,
 LSGD Section,
 Ezhukone G.P.