

FITNESS CERTIFICATE OF SCHOOL BUILDING

[To be filled by the Inspecting Officer (Assistant Engineer)]

1. Name of School *Pree Narayana Guru Central School, Ezhubra*
2. Location with name of Education District *Kottarakkall Education District*
3. Whether the fitness certificate has been issued last year? *Yes*
4. Classification of the buildings Permanent/ (I) Temporary shed? *Permanent buildings*
3 storaged RCC buildings
5. Year of construction *2019-20*
6. Short specification
GF (class) 2.22 x 6.20 x 3.75m - 5 Nos.
(1st) 10.15 x 6.20 x 3.75m - 2 Nos
Stair case 3.0 x 6.20 x 3.75m - 2 Nos.
Store 2.10 x 6.20 x 3.75m - 2 Nos
porch 6.48 x 8.48 x 3.70m
passage 3.28 x 2.40 x 3.75m
2 x 6.71 x 2.40 x 3.75m
7. Whether regular maintenance works attended to or not? *Yes*
8. Name of officer *Sandhya V.S.*
9. Period for which the certificate issued *2020-21*
10. Nature of defects if any? (II) *3 storaged RCC Buildings*
GF 2 x 16.30 x 6.60 x 3.60m
1 x 29.0 x 6.60 x 3.60m
passage 1 x 29.0 x 1.85 x 3.60m
porch 1 x 6.50 x 4.60 x 3.60m
EF 2 x 16.30 x 6.60 x 3.60m
1 x 29.0 x 6.60 x 3.60m
over porch 1 x 6.50 x 4.60 x 3.60
SF 2 x 16.30 x 6.60 x 3.60m
1 x 29.0 x 6.60 x 3.60m
passage 1 x 29.0 x 1.85 x 3.60m
 (III) *Office building - 1 x 12.00 x 6.20 x 3.60m*
(single storaged RCC building)
11. Any major defects noticed which will render the building unsafe if any manner *No*
12. Whether maintenance works have been done properly? *Yes.*
13. Whether the structure is sound or not to conduct classes? *The above buildings are structures fit for conducting classes only under normal wind and weather conditions.*

Inspected that the building was inspected on *29/05/2020*
 and found to be fit/safe to conduct classes for the period for *2020-21*
Beedam V.S. for the reasons stated above.

Ezhubra

29/05/2020

Signature

Designation

[Signature]
29/5/2020